




# Assembly Flow Chart



**P-40 WARHAWK**

## 3D METAL MODEL KITS




- Legends:**
- E** Engraved / Color side
  - NE** Non-engraved / Silver side
  - Attention point
  - Insert tab and bend 90 degrees
  - Insert tab and twist 90 degrees

- Recommended tools:**
- Wire cutters: helpful for taking parts from the metal sheets.
  - Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.

**Assembly tip:**  
If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish

## Metal sheets

Parts that are in the same color are duplicates



**!** In order to avoid possible injury from sharp edges, please carefully discard the metal sheets after parts have been removed

